

Layered Christmas Tree, 18 in



A tabletop Christmas tree in steel, about 18 inches tall: six eight-point star tiers drop onto a cross-shaped spine, each stopping on its own ledge, with a star on top. Every point has a hole for an ornament or lights. No tools, no welding, and it comes apart flat to store.

What's in the box




Spine B x1
Part TR18-01



Spine A x1
Part TR18-02



Star tier 1 x1
Part TR18-03



Star tier 2 x1
Part TR18-04




Star tier 3 x1
Part TR18-05



Star tier 4 x1
Part TR18-06



Star tier 5 x1
Part TR18-07



Star tier 6 x1
Part TR18-08




Topper star x1
Part TR18-09

What you'll need

- No tools needed

1 Cross the spine




Stand spine B (TR18-01) on its feet, its slot opening at the top. Hold spine A (TR18-02) square across it, its slot opening down, line the slots up and slide A down until both stand on the table.

TIP

Spine A is the one with the tall fin on top.

2 Drop on the star tiers, biggest first



Lower the biggest star tier (TR18-03) over the top of the spine, its + slot over the cross, and let it drop. It stops on its own ledge. Do the same with each next-smaller tier: each one stops on the ledge above the last.

TIP

Every tier's slot fits only above its own ledge, so they can't go on at the wrong height.

Turn each tier so its points sit between the points of the one below.

3 Top it with the star



Slide the topper star (TR18-09) down onto the fin at the top, the slit in its stem straddling the fin, until it sits on the fin.

TIP

Hang ornaments or a string of LED lights from the holes in the points.

Finishing

- The parts ship bare with a light oil film. Wipe them down before you paint.
- Paint the parts before you put the tree together: forest green, white, gold, or satin black. Or clear-coat the bare steel.
- Felt pads under the four feet protect a table.

Safety

- Decor only: it isn't a toy, and the star points are steel. Keep it where small children can't pull it over.
- Use LED lights only, never candles, on or near it.
- Set it on a flat, level table; the bottom tier is 14" across.

This is a kit of raw steel parts that slots together. How you assemble it and where and how you use it are yours to judge. If you weld it, use proper ventilation and protective gear.